



Remanufactured Range Rover Valve Block

A common problem with the Range Rover EAS is bad seals in the valveblock and line connection to the air springs. Our remanufactured Range Rover Electronic Air Suspension "EAS" Valve Blocks are the solution.

Product Description

Our remanufactured EAS valve blocks start with an OEM core and go through several processes in our Black Dog Reman Department. Each valve block core receives a thorough cleaning and detailed inspection prior to being reassembled with a complete set of new o-rings. After assembly each unit is then visually inspected and fully tested for consistent air pressure as well as operational functionality.

EAS valve blocks fit 1995-2002 Range Rover 4.0SE & 4.6HSE models.

Features & Benefits

- Meets or Exceeds OEM Specifications
- Less Expensive than an OEM Replacement Unit
- All Original O-rings are Replaced with New Ones
- Fully Tested for Consistent Pressure & Operational Functionality
- 12 month warranty

Part# & Application

RVH100030R - 1995-2002 4.0SE & 4.6HSE